

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans **Run date** 21-Nov-14 **Time** 10:10 PM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 163 Const Calendar Day: 65 Date: 08-Aug-2012 Wednesday Inspector Name: Altamirano, Victor Title: Transportation Engineer

Inspection Type:

Shift Hours: Break: Over Time:

Federal ID: Location:

Reviewer: Schmitt, Alex Approved Date: Status: Submit

Weather

Temperature 7 AM 50 - 60 **12 PM** 50 - 60 **4PM** 50 - 60

Precipitation Condition

Working Day 🗹 If no, explain:

Diary:

Cable Band Activities

Inspector: Victor Altamirano (8 hours reg.)

Date: 080812

Field Work:

(1) Gary's crew de-tensioned and adjusted cable band 98N given that the cable band was not installed in the correct position in the longitudinal direction and the rotation centerline was out-of-tolerance. Refer to Doug W. diary for detail of the work given that I was in the warehouse at Pier 7 with Roman G. when I was informed that the cable band was shifted. Refer also to my diary from yesterday.

Office Work: Worked on diaries.